DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES Office of Structural Materials

Quality Assurance and Source Inspection

Bay Area Branch 690 Walnut Ave.St. 150 Vallejo, CA 94592-1133 (707) 649-5453 (707) 649-5493



Contract #: 04-0120F4

Cty: SF/ALA Rte: 80 PM: 13.2/13.9

File #: xx.28

WELDING INSPECTION REPORT

Resident Engineer: Siegenthaler, Peter **Report No:** WIR-020772 Address: 333 Burma Road **Date Inspected:** 16-Jul-2010

City: Oakland, CA 94607

OSM Arrival Time: 700 **Project Name:** SAS Superstructure **OSM Departure Time:** 1900 **Prime Contractor:** American Bridge/Fluor Enterprises, a JV

Contractor: Zhenhua Port Machinery Company, Ltd (ZPMC), Changxing Island **Location:** Shanghai China

CWI Name: CWI Present: Yes Mr.Liu Huajie. No **Inspected CWI report:** Yes N/A **Rod Oven in Use:** Yes No No N/A Yes N/A **Electrode to specification:** No **Weld Procedures Followed:** Yes No N/A N/A **Qualified Welders:** Yes No **Verified Joint Fit-up:** Yes No N/A N/A Yes N/A **Approved Drawings:** Yes No **Approved WPS:** No Yes No N/A **Delayed / Cancelled:**

34-0006 **Bridge No: Component: OBG** Trial assembly

Summary of Items Observed:

On this day CALTRANS OSM Quality Assurance (QA) Inspector Raghavendra Reddy was present during the times noted above for observations relative to the fabrication of the SAS Superstructure being performed by Zhenhua Port Machinery Company (ZPMC) at Changxing Island in Shanghai, China. QA observed and/or found the following:

This QA Inspector observed the following work in progress:

SEGMENT # 9E:

Flux Cored Arc Welding (FCAW) of weld joint SP376-01~08(9DE to 9EE), Welder is identified as 067942. ZPMC Quality Control (QC) is identified as Mr. Liu Huajie. The welding variables appeared to comply with the Applicable WPS: WPS-B-T-2132.

FCAW Welding of weld joint SP709-001-031~035(9DE to 9EE), Welder is identified as 068493. ZPMC Quality Control (QC) is identified as Mr. Liu Huajie. The welding variables appeared to comply with the Applicable WPS: WPS-B-T-2233T.

FCAW Welding of weld joint DP700-001-019,020 (9DE to 9EE), Welder is identified as 066258. ZPMC Quality Control (QC) is identified as Mr. Liu Huajie. The welding variables appeared to comply with the Applicable WPS: WPS-B-T-3213-B-U3b.

WELDING INSPECTION REPORT

(Continued Page 2 of 2)

SEGMENT#9W

Shielded Metal Arc Welding (SMAW) welding of weld joint OBW9-010 (9CE-9DE). Welder is identified as 066326. ZPMC Quality Control (QC) is identified as Mr. Xu Jin Lang. The welding variables appeared to comply with the Applicable WPS-B-P-2214-B-U2-FCM-1

FCAW Welding of weld joint OBW9B-007 (9BW to 9CW), Welder is identified as 069683. ZPMC Quality Control (QC) is identified as Mr. Xu Jin Lang. The welding variables appeared to comply with the Applicable WPS: WPS-B-T-2233T-1

FCAW Welding of weld joint OBW9B-009 (9BW to 9CW), Welder is identified as 066239. ZPMC Quality Control (QC) is identified as Mr. Xu Jin Lang. The welding variables appeared to comply with the Applicable WPS: WPS-B-T-2233T-1

The following Non Destructive Testing (NDT) Inspection carried out as per the ZPMC submitted Notification No. 06212

Magnetic Particle Testing (MT)

This QA Inspector performed MT of approximately 15% of the area previously tested and accepted by ZPMC Quality Control personnel. This QA Inspector generated a MT report for this date. The member is identified as Internal Diaphragm Under FL3 weld. The weld designations reviewed are as follows.

1.SSD27-PP75-167~170,172,174,175,176,119~124,127,128,089,090, 093~098,103,104,063,065,059,061,062,066, 025~028,023,024,030,031,021,022,091,092,165,166.

Unless otherwise noted, all work observed on this date appeared to be in general compliance with the applicable contract documents.

Summary of Conversations:

Only general conversation was held between QA and QC concerning this project.

Comments

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Michael Ng (15921845703), who represents the Office of Structural Materials for your project.

Inspected By:	Tharikoppada,Reddy	Quality Assurance Inspector
Reviewed By:	Miller,Mark	QA Reviewer